National Transportation Safety Board NTSB ID: ANC95LA023 Aircraft Registration Number: N242SS FACTUAL REPORT Occurrence Date: 01/02/1995 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone **CRAIG** ΑK 99921 1035 AST Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

CESSNA

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On January 2, 1995, at 1035 Alaska standard time, a float equipped Cessna model 208 (Caravan) airplane, N242SS, operated by Taquan Air Service of Ketchikan, Alaska as scheduled flight No. 2, sustained substantial damage when it collided with a partially submerged log during a high speed water taxi from landing at Craig, Alaska. The airline transport certificated pilot-in-command, and the seven revenue passengers aboard were not injured. The 14 CFR Part 135 flight departed Ketchikan at 0955, and the destination was Craig. Visual meteorological conditions prevailed, and a VFR flight plan was on file.

208

The pilot reported that prior to landing he surveyed the area and thought it safe to perform a landing. He wrote in his report to the NTSB that the bright sunlight and approximately one foot of convection fog covering the water surface were restrictions to his visibility. Just after coming off a step taxi, he said the right float struck a log, which damaged the right float, and caused the airplane to veer to the right. The resultant side loads on the left float caused it to collapse, and the left wing was damaged when it struck the water.

Airplane

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC95LA023

Occurrence Date: 01/02/1995

AVIATION		Occurrence Type: Accident			Accident								
Landing Facility/Approach Info	ormation												
Airport Name			Airport ID	D: [Airport Eleva	tion	Run	way Used	Runwa	y Lengt	h F	Runw	ay Width
					Ft.	MSL	0						
Runway Surface Type:													
Runway Surface Condition:													
·													
Type Instrument Approach: NONE													
VFR Approach/Landing: Full Stop													
Aircraft Information													
Aircraft Manufacturer			1 1	del/S	eries						Number		
CESSNA			20)8 ——						0009	6		
Airworthiness Certificate(s): Normal													
Landing Gear Type: Float													
Homebuilt Aircraft? No Number of Seats: 10				Certified Max Gross Wt.					8210 LBS Numbe			er of Engines: 1	
			Engine P&W	Engine Manufacturer: Model/Series: P&W PT6A-114							Rated 600	d Power: HP	
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection Time			Time Si	ne Since Last Inspection				e Tota	al Time	
AAIP 1:			12/22/1994 18 Hor					urs	urs 4982 Hours				
- Emergency Locator Transmitter (E	LT) Information												
ELT Installed? Yes	ELT Installed? Yes ELT Operated? No ELT Aided in Locating Accident Site?												
Owner/Operator Information													
Registered Aircraft Owner Street Address 1007 WATER STREET													
TAQUAN AIR SERVICE			City								State		Zip Code
			KETCHIKAN Street Address							AK	!	99901	
Operator of Aircraft			Stree	et Ado		Rea	'd Aircr	aft Owner					
Same as Reg'd Aircraft Owner			Same as Reg'd Aircraft Owner City						State		Zip Code		
Operator Does Business As: Operator Designator Code: FYWA													
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s):	Commuter Air Ca	arrier											
					T								
Operating Certificate:	_				Operator C	ertific	cate:						
Regulation Flight Conducted Under:		xi & Co	ommutei	r									
Type of Flight Operation Conducted:	Unknown												
	J	FACTU	JAL RE	POR	T - AVIATI	ON							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC95LA023

Occurrence Date: 01/02/1995

AVIAT	Occurrence Type: Accident											
First Pilot Information												
Name City									Sta	ate	Date of Birth	Age
On File On Fil							ile			File	On File	26
Sex: M Seat Occupied: Left Principal Profession: Civilian Pilot								C	ertifica	te Numl	ber: On File	
Certificate(s): Airline Transport												
Airplane Rating(s): Multi-engine Land; Single-engine Land; Single-engine Sea												
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): Airplane												
Instructor Rating(s): Airplane Single-engine; Instrument Airplane												
Type Rating/Endorsement f	or Accident/Ir	ncident Aircra	ft? No			Cı	urrent Bien	nial Flight	Revie	w?		
Medical Cert.: Class 2	Medica	al Cert. Status	s: Valid Med	dicalw/ wai	ivers/lim			Date of I	_ast M	edical E	Exam: 01/17/19	94
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Nig			Instr Actual	ument Simulated	i	Rotorcraft	Glider	Lighter Than Air
Total Time	4331	100	4309	22	1	07	60) 1	64			
Pilot In Command(PIC)	4282	100	4277	5	_	04	60	_	64			
Instructor	1247	3	1247			35	30)	80			
Last 90 Days	68	25	68			_	1		4			
Last 30 Days Last 24 Hours	25	12 1	25 1			\dashv		1	+			
Seatbelt Used? Yes	' 	ılder Harness			To	oxico	logy Perfor	med? No		s	econd Pilot? No)
Flight Plan/Itinerary												
Type of Flight Plan Filed: V	FR											
Departure Point					s	State Ai		Airport Identifier		Departure Time		Time Zone
KETCHIKAN						AK 5K		5KE		0955		AST
Destination	Destination State Airport Identifier											
Same as Accident/Incident Location CGA												
Type of Clearance: None												
Type of Airspace: Class	G											
Weather Information												
Source of Briefing:												
Method of Briefing:												
			FACTUAL	REPORT -	AVIAT	ION	1					Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC95LA023

Occurrence Date: 01/02/1995

Occurrence Type: Accident

	FTYBON				o . , p o.	7100100						
Weather	Information											
WOF ID	Observation Time	Time Zone	WOF	Elevati	on	WOF Distance From Accident Site			Direction From Accident Site			
	0000			0 Ft.	MSL	0 NM				0 Deg. Mag.		
Sky/Lowes	st Cloud Condition: Clear	-					0 Ft.	AGL	Condition o	f Ligh	nt: Day	
Lowest Ce	Lowest Ceiling: None 0 F				AGL	Visit	oility:	50	SM	Altimeter:		"Hg
Temperatu	Temperature: -2 °C Dew Point: °C Wind Direction: Density Altitude:							Ft.				
Wind Spee	Wind Speed: Light and Variable Gusts: Weather Condtions at Accident Site: Visual Conditions											
Visibility (F	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensi	ty of Pred	cipitation:	Unknown			
Restriction	Restrictions to Visibility: Fog											
Type of Precipitation: None												
Accident	Information											
Aircraft Damage: Aircraft Fire: Aircraft Explosion												
Classificati	on:											
- Injury Su	mmary Matrix	Fatal	Serious	Mino	r	None	TOTAL					
First Pi	lot					1		1				
Second	d Pilot											
Studen	t Pilot											
Flight I	nstructor											
Check	Pilot											
Flight E	Engineer											
Cabin A	Attendants											
Other 0	Crew											
Passer	ngers					7	,	7				
- TOTAL A	ABOARD -							8				
Other 0	Ground	0	(0			0				
- GRANE	O TOTAL -	0			0	8	3	8				
				-	•		•					

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: A	NC95LA023
------------	-----------

Occurrence Date: 01/02/1995

Occurrence Type: Accident

istrative	

Investigator-In-Charge (IIC)

TIMOTHY A. BORSON

Additional Persons Participating in This Accident/Incident Investigation:

JAMES MC COY FAA, 1873 SHELL SIMMONS DR. JUNEAU, AK 99801